# Downtown Flagler Street Beautification Project

Recap of work done in the month of February 2024

# Milestones achieved in February 2024

# Phase A (Biscayne Blvd to E 3<sup>rd</sup> Ave)- Substantial Completion

- Punch List items still pending.
- Foundation completed and concrete poured for pedestrian railing.
- Installed sidewalk pavers and pavers in deterrent area on the NW corner of Biscayne Blvd.

# Phase B (E 3<sup>rd</sup> Avenue to E 2<sup>nd</sup> Ave)- Substantial Completion

- Punch List items still pending.
- Replaced detectable warning pavers.


# Phase C (E 2<sup>nd</sup> Ave to 1<sup>st</sup> Ave)

- Installed roadway way pavers.
- Installed sidewalk pavers.
- Installed hard scape furniture.
- Installed sidewalk tiles for businesses.

# Phase D (E 1<sup>st</sup> Ave to N Miami Ave)

- Excavating for tree pits.
- Installing oak trees.
- Installed streetlight poles.
- Installed luminaries on to street light poles.

- Placed organic material for landscaping.
- Placed concrete for trench drain tie in.
- Placed concrete for tree pit grate footer.
- Placed concrete for black bands on sidewalk.
- Installed conduits for streetlight poles.
- Installed conduit for receptacles.
- Demo sidewalk on North side.
- Installed PVC pipe for roof drain.



#### **Phase A** (Biscayne Blvd to E 3<sup>rd</sup> Ave)

 Installed sidewalk pavers and pavers in deterrent area on the NW corner of Biscayne Blvd.

#### **Phase A** (Biscayne Blvd to E 3<sup>rd</sup> Ave)

• Grading material and installed sidewalk pavers.





#### **Phase A** (Biscayne Blvd to E 3<sup>rd</sup> Ave)

• Placed concrete for curb ramp on the NW corner of Biscayne Blvd.




• Installed detectable warning pavers for crosswalk.



• Placed concrete for black bands on sidewalk.


• Installing hardscape furniture.





• Installed twisted bollards.


• Installed roadway pavers.



• Preparation of valet area.

• Placed concrete for tree grate footer.





• Installed sidewalk pavers in deterrent area.





• Installed sidewalk tiles for businesses.

• Installed filter fabric and tree grate.





• Grading material and installing forms for tree grate footer.

• Excavating material for tree pits.





• Installed Oak trees on northside of Flagler Street.



• Saw cutting sidewalk in preparation of sidewalk demolition.

• Installing forms for trench drain tie in.





• Installation of street light poles.